

Single Event Effects Characterization of Dosed UT200SpWPHY01 SpaceWire Physical Layer Transceiver

Sergeh Vartanian, Gregory R. Allen, *Member, IEEE*, Farokh Irom, and Leif Z. Scheick, *Member, IEEE*

Abstract—We present SEE test results for the Cobham SpaceWire transceiver after dosing the device to 300 krad(Si). We performed SEU characterization with variable data rates and patterns. Events resembling SEFIs were also observed and recorded.

I. INTRODUCTION

SPACEWIRE is a standardized spacecraft data handling and communication network based on the IEEE 1335 standard; it is simple to implement, relatively high speed, low power, and robust [1]. Therefore, it has been adopted and widely used by ESA, NASA, and JAXA for many significant missions. Cobham's UT200SpWPHY01 PHY transceiver is designed to handle the critical timing issues associated with the SpaceWire data and strobe encoding method and eliminate the use of standalone Low-Voltage Differential Signaling (LVDS) drivers and receivers. This chip is manufactured on a 250 nm logic EPI silicide silicon Complementary Metal-Oxide Semiconductor (CMOS) process at a TSMC foundry. According to Cobham, this device has been successfully tested up to 100 krad(Si) total dose per MIL-STD-883 Method 1019 and has proven to be immune to latch-up at high Linear Energy Transfer (LET), ($LET > 109 \text{ MeV-cm}^2/\text{mg}$) [2].

This data workshop presents complete heavy ion induced Single Event Upset (SEU) characterization data for the SpaceWire PHY transceiver (UT200SpWPHY01). The SEU cross-section for this device is small based on Cobham's SEE qualification report [3]. They reported a saturated cross-section of about $1\text{E-}7 \text{ cm}^2$ and LET threshold of $38 \text{ MeV-cm}^2/\text{mg}$. Additionally, they described seeing events resembling Single Event Functional Interrupts (SEFIs) where bursts of multiple

bit-errors occurred. The main differences between our test and Cobham's are the data transmission rate and pattern, the wider range of heavy ions used, greater beam fluence, and the fact that our parts were pre-dosed to 300 krad(Si) for harsh radiation environment mission compatibility. They tested at a constant, low transmission rate of 24 Mbps while we tested at 240, 200, and 50 Mbps, which resulted in lowering the LET threshold, increasing the SEU cross-section, and recording numerous "burst" events or SEFIs.

II. EXPERIMENTAL PROCEDURE

A. Device Features

The device features include 2-bit Serializer/Deserializer (SerDes) functionality, transmit and receive rates of 200 Mbps or more, 3.3V supply voltage (V_{DD}), radiation-hardened design, and 28-pin flatpack ceramic package. All control, clock, and single ended data signals to the device are 3.3V Low-Voltage CMOS (LVCMOS) input/output type while all transceiver signals are low voltage differential signaling (LVDS) pairs [2]. The device block diagram is shown in Figure 1.




Figure 1. UT200SpW PHY Chip Block Diagram

B. Test Samples

Two test samples were irradiated to 300 krad(Si) in the Cobalt-60, high dose rate cell at JPL with a 20 rad(Si)/s dose rate. The samples were dosed approximately a week before the SEE test. Supply currents for both devices were measured and recorded for pre and post irradiation; functional tests were also performed. Our test samples consisted of 1 biased, 1 unbiased condition parts, and 2 virgin parts for control. The test samples are shown in Table I.

Table I. UT200SpWPHY01 300 krad(Si) Dosed SEE Test Samples

SN	TID Test Condition	Date Code	TID Level krad(Si)
4401	biased (3.6V)	1718	300
4406	unbiased (Ground)	1718	300

The research was carried out at the Jet Propulsion Laboratory, California Institute of Technology, under a contract with the National Aeronautics and Space Administration. © 2018 California Institute of Technology. Government sponsorship acknowledged. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not constitute or imply its endorsement by the United States Government or the Jet Propulsion Laboratory, California Institute of Technology. All rights reserved.

S. Vartanian is with the Jet Propulsion Laboratory, California Institute of Technology, Pasadena, CA 91109 USA (phone: 818-354-0311; e-mail: sergeh.vartanian@jpl.nasa.gov).

G. R. Allen is with the Jet Propulsion Laboratory, California Institute of Technology, Pasadena, CA 91109 USA (phone: 818-393-7558; e-mail: grallen@jpl.nasa.gov).

F. Irom is with the Jet Propulsion Laboratory, California Institute of Technology, Pasadena, CA 91109 USA (phone: 818-354-7463; e-mail: farokh.irom@jpl.nasa.gov).

L. Z. Scheick is with the Jet Propulsion Laboratory, California Institute of Technology, Pasadena, CA 91109 USA (phone: 818-354-3272; e-mail: leif.z.scheick@jpl.nasa.gov).

causes the bit error counter in our FPGA firmware to increment by 1. It does not require a hard reset (resets the PHY chip and the FPGA data transmission), and it is most likely a common flip-flop or latch upset. The “single” SEU versus LET cross-sections for both devices are shown in Fig. 6 and 7.




Figure 6. Unbiased Device “Single” SEU Cross-Section as a Function of LET




Figure 7. Biased Device “Single” SEU Cross-Section as a Function of LET

The “burst” bit-errors/events that we detected can be split into two categories. In the first case, the bit-error counter increments or jumps by a random number generally in the range of two to a few thousands bit errors and the data transmission continues without further errors or the need to initiate a reset. For the second case, the counter increments uncontrollably and does not recover on its own. This bit-error runaway case requires a reset before continuing with the test; this case can be considered as a SEFI [5]. This event is most likely caused by an upset to the recovered clock (RxClk) path of the DUT which could result in a missed clock edge that could further cause misalignment between the receive data and clock going to the FPGA. The “burst” SEU versus LET cross-sections for both devices are shown in Fig. 8 and 9.




Figure 8. Unbiased Device “Burst” SEU Cross-Section as a Function of LET




Figure 9. Biased Device “Burst” SEU Cross-Section as a Function of LET

Although the failure or error profile of the burst events is more like SEFIs than SEUs, we categorized each burst event as a SEU (Cobham used a similar approach in their report). We call these combined SEUs “Total” cross-sections, which are shown in Fig. 10 and 11. This not only helps us calculate a more accurate rate; it also allows us to remove any confusion or questions since the device mechanism for the cause of the burst event is unknown and somewhat unpredictable. Furthermore, it is our understanding that the SpaceWire protocol can be interrupted (dropped link) by even a single bit error in a packet during transmission, which requires re-instantiating the link and restarting data transmission. It is highly recommended to perform device reset every time the link is dropped or a bit error is detected. “Burst” events were reported as rare events in Cobham’s SEE report. However, for our SEU cross-sections, burst events are for the most part the dominant events and the reason behind the bigger SEU cross-section. The sudden increase in the number of burst events/SEFIs is directly correlated with the faster clock/data rate we operated our test setup compared to Cobham’s 24 MHz. At higher clock rates, it is much more likely to observe

clock and data transients. The SEU test results are listed in Table III.




Figure 10. Unbiased Device "Total" SEU Cross-Section as a Function of LET




Figure 11. Biased Device "Total" SEU Cross-Section as a Function of LET

Table III. Summary of SEU Test Results

Device	SEU Threshold (MeV-cm ² /mg)	SEU Saturation Cross-Section (cm ² /device)
UT200SpWPHY	< 19.6	1x10 ⁻⁶

IV. CONCLUSION

The SEU cross-section in general for this device is small based on both Cobham's and our SEE test results. While the single bit error cross-section is slightly frequency dependent, the SEFI or burst event cross-section is highly dependent on the transmission rate (clock speed). Based on our results, the 300 krad(Si) total dose did not have any significant effect on our results as expected for a simple, rad-hard CMOS technology device. Also, there were certainly no distinguishable difference between the two samples. For SEE rate calculation, it is highly recommended to use the data from the "Total" SEU cross-section.

REFERENCES

- [1] S. Parkes. (2012). "SpaceWire User's Guide" [Online]. Available: <https://www.stardundee.com/sites/default/files/SpaceWire%20User%27s%20Guide.pdf>.
- [2] Aeroflex, "SpaceWire Physical Layer Transceiver Datasheet," UT200SpWPHY01, February 2008.
- [3] C. Hafer, "Single Event Effects Qualification Summary for the UT200SpWPHY01 SpaceWire Physical Layer Transceiver," Aeroflex, Colorado Springs, CO, June 2006.
- [4] "Radiation Effects Facility, Cyclotron Institute, Texas A&M University," [Online]. Available: <http://cyclotron.tamu.edu/ref/>. [Accessed 17- Jan-2017].
- [5] M. D. Berg, "Example 1: Trading ASIC and FPGA considerations for system insertion," presented at the IEEE Nuclear and Space Radiation Effects Conf. Short Course, 2009.